



Kirby Morgan Dive Systems, Inc.®

1430 Jason Way, Santa Maria, California 93455

Phone: 805/928-7772 Fax: 805/928-0342

www.kirbymorgan.com e-mail: kmdsi@kirbymorgan.com

Bulletin #8 of 2020. August 10, 2020

CHANGE TO PRODUCT BULLETIN

P/N 530-099 Cover Retainer Screw and

P/N 550-074 Bishop Pin Now Bronze

Products Affected: 500-710 KM Diamond Helmet w/Posts, 500-711 KM Diamond Helmet w/MWPC, 500-700 KM 97 Helmet w/Posts, 500-701 KM 97 Helmet w/MWPC, 505-086 Regulator Cover Retainer Assembly, 505-373 Regulator Cover Assembly, 525-761 KM 97 Water Shroud Kit and 505-455 (525-756) 455 Balanced regulator

The Cover Retainer Screws and Bishop Pins that are used to secure the Regulator Cover Retainer Assembly to the Diamond POD and 455 Balanced Regulator body are now made out of bronze. This change in material has been made to prevent stainless steel galling.

We will be shipping the P/N 530-099 Cover Retainer Screw and the P/N 550-074 Bishop Pin made out of Bronze effective immediately.



Previous stainless steel and current bronze P/N 550-074 Bishop Pin, left and previous stainless steel and current bronze P/N 530-099 Cover Retainer Screw, right.

The part number will remain the same and no change to associated procedures for maintenance of the screw is necessary.

Kirby Morgan recommends upgrading all stainless steel Cover Retainer Screws and Bishop Pins on all existing units to avoid possible galling in the future.

Please contact your authorized KMDSI dealer or e-mail kmdsi@kirbymorgan.com for more information.

