



# Kirby Morgan Dive Systems, Inc.®

1430 Jason Way, Santa Maria, California 93455

Phone: 805/928-7772 Fax: 805/928-0342

www.kirbymorgan.com e-mail: kmgsi@kirbymorgan.com


**Bulletin #8 of 2022. June 20, 2022**

## **CHANGE TO PRODUCT BULLETIN**

### **P/N 540-095 Packing Washer Now 316L Stainless Steel**

**Products Affected:** Side Block Assembly P/N 505-024 (Chromed), 505-025 (Brass) and Manifold Block Assembly P/Ns 300-145, 300-150, 300-155. 505-070 Emergency Valve Assembly, 505-080 Emergency Valve Assembly, Brass, 325-095 Manifold Block Rebuild Kit, 525-217 KM 57 Soft Goods Overhaul Kit, 525-311 Side Block Rebuild Kit, 525-356 SL 17C, 17K, KM 37 and 57 with 455 Regulator Soft Goods Overhaul, 525-358 KMB 18/28 Soft Goods Overhaul with SuperFlow® 350 Regulator, 525-359 SL 27® with 455 Regulator Soft Goods Overhaul Kit, 525-360 SL 17A/B Soft Goods Overhaul Kit, 525-363 SL 17C, 17K and KM 37 Soft Goods Overhaul Kit, 525-365 SL 27 Soft Goods Overhaul Kit with SuperFlow® 350 Regulator, 525-367 KMB 18/28 with 455 Regulator Soft Goods Overhaul Kit, 525-368 KM 47 Soft Goods Overhaul Kit

Switching from brass to stainless steel material will reduce the difference in the electrode potential between the Packing Washer and the Valve Stem adding to the longevity of the components.



*Current P/N 540-095 Packing Washer, left and center left, and previous, center right and right.*

Any old stock of the Packing Washer can be used without issue.

No change in part numbers.

No change in price at this time.

There will be no exchanges offered.

Please contact your authorized KMDSI dealer or e-mail [sales@kirbymorgan.com](mailto:sales@kirbymorgan.com) for more information.

